


FIG. 1
PRIOR ART



661030" 24152260

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG. 2
PRIOR ART






FIG. 3 PRIOR ART



600900-2-1000000

FIG. 4



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN:		

FIG. 5A




FIG. 5B






FIG. 6



644930" 644930" 644930"


FIG. 7



6610990 243260

FIG. 8

SPECIAL-PURPOSE



667090 213600

FIG. 9






FIG. 10A



ABNORMAL CONDITION IN SPACE DIVISION SWITCH


FIG. 10B



ABNORMAL CONDITION IN CENTRAL CONTROL UNIT


61030" 4713220

FIG. 11A



ABNORMAL CONDITION IN CONTROL BUS 550

FIG. 11B



ABNORMAL CONDITION IN TDM LINES 300, 301, ..., 31n

FIG. 12




FIG. 13A




FIG. 13B





FIG. 14



641090" 2125200